

Multi-Section Poly Flighting ASSEMBLY INSTRUCTIONS

PLEASE READ THE ENTIRE INSTRUCTION SHEET BEFORE STARTING INSTALLATION.

Please refer to the manufacturer's operator's manual for pertinent safety precautions. **THINK SAFETY. WEAR SAFETY GLASSES.**



Multi-Section Poly Flighting Assembly Instructions

1. Remove the bolt from the tube section to be joined to the All-Hex Connector.
2. With the flight edges lined up, slide the All-Hex Connector into the section.
3. Where the flighting edges meet, use a putty knife to spread them apart while sliding the two sections together.
4. Use a punch to help line up the holes in the sections and the All-Hex Connector.
5. Replace the bolt and lock nut, making sure not to over tighten against the Poly Flight hub.

WARNING Proper application, installation and operation of any machine and/or installation incorporating products sold by May Wes Mfg. is the responsibility of the purchaser and/or end user. All local, state and federal safety codes must be followed. May Wes Mfg. is specifically not responsible for property damage and/or personal injury, direct or indirect, for damages and/or failures caused by improper design, application, installation, operation, abuse and/or misuse of its' products. Conveyors must never be installed, readied for operation, or operated without proper covers and guards installed and securely in place.



1-800-788-6483